

NOTICE ABOUT YOUR DRINKING WATER

Treatment Requirements Not Met

Public Water System Name: Andover Village District PWS ID 0081010: _____

We routinely monitor for the disinfectant residual in the water leaving the treatment plant. The disinfectant residual is the amount of chlorine or related disinfectant present in the water. This measurement shows that the water supply is effectively being disinfected. If the disinfectant residual is too low, organisms could grow in the water system. The disinfectant residual level may not drop below 0.2 mg/L for more than four (4) hours.

The disinfectant residual dropped below 0.2 mg/L on:

Date(s)	Number of hours below 0.2 mg/L
5-26-2025	3 @ .16

What should I do? This is not an emergency. If it had been, you would have been notified immediately.

Monitoring results during this time period **did / did not X** indicate the presence of bacteria in the water.
(circle one)

Inadequately treated water may contain disease-causing organisms. These organisms include bacteria, viruses, and parasites, which can cause symptoms such as nausea, cramps, diarrhea, and associated headaches.

It is not necessary to use alternate water; however, if you have specific health concerns, please contact your health care professional. General health related questions may be directed to the EPA Safe Drinking Water Hotline at 1-800-426-4791.

Steps being taken to correct the situation: Relay failure at the water plant. New unit was installed.

Expected Resolution Date: 5/27

Contact Name: John Coffey Company: Andover Village District

Address: PO Box 185 Canaan, N.H. 03741 Telephone Number: 603-304-9380

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example; people in apartments, nursing homes, schools and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

NOTICE ABOUT YOUR DRINKING WATER

Treatment Requirements Not Met

Public Water System Name: Andover Village District PWS ID 0081010: _____

We routinely monitor for the disinfectant residual in the water leaving the treatment plant. The disinfectant residual is the amount of chlorine or related disinfectant present in the water. This measurement shows that the water supply is effectively being disinfected. If the disinfectant residual is too low, organisms could grow in the water system. The disinfectant residual level may not drop below 0.2 mg/L for more than four (4) hours.

The disinfectant residual dropped below 0.2 mg/L on:

Date(s)	Number of hours below 0.2 mg/L
5-26-2025	3 @ .16

What should I do? This is not an emergency. If it had been, you would have been notified immediately.

Monitoring results during this time period **did / did not X** indicate the presence of bacteria in the water.
(circle one)

Inadequately treated water may contain disease-causing organisms. These organisms include bacteria, viruses, and parasites, which can cause symptoms such as nausea, cramps, diarrhea, and associated headaches.

It is not necessary to use alternate water; however, if you have specific health concerns, please contact your health care professional. General health related questions may be directed to the EPA Safe Drinking Water Hotline at 1-800-426-4791.

Steps being taken to correct the situation: Relay failure at the water plant. New unit was installed.

Expected Resolution Date: 5/27

Contact Name: John Coffey Company: Andover Village District

Address: PO Box 185 Canaan, N.H. 03741 Telephone Number: 603-304-9380

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example; people in apartments, nursing homes, schools and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.